## 7. Packing Diagram and Parts List




| Location | Code No. | Description | Specification | Q¡fty | Remarks |
|---|---|---|---|---|---|
| 1 | DJ69-40162A | PAD - UP | SW2. | 1 | |
| 2 | DJ69-60151A | PACKING - INNER | EPS | 1 | |
| 3 | DJ69-40163A | PAD - LOW | DW2 | 2 | |
| 4 | DJ67-50146H | PIPE - STEEL | STEEL | 2 | |
| 5 | DJ69-10153A | PACKING - CASE | SW3 - A | 1 | |
| 6 | VC-6713H | VACUUM CLEANER | 230V, 50Hz | 1 | |
| 7 | DJ68-40145C | INSTRUCTION - E | MOJOJI | 1 | |
| 8 | DJ67-40155A | HOSE - ASS'Y | ASS'Y | 1 | |
| 9 | DJ74-10117G | BAG - PAPER ASS'Y | ASS'Y | 1 | |
| 10 | DJ67-60178C | BRUSH - ASS'Y | ASS'Y | 1 | |
| 11 | DJ67-60002B | DUSTING - BRUSH ASS'Y | ASS'Y | 1 | |



MEMO